




HEAVIEST LOADED BAY WITHIN THE SCS SPACE ON
THE THIRD FLOOR

PHOTO # 33



ROOM 3100, ATF GUN VAULT

PHOTO # 34



DEFLECTION IN FLOOR EVIDENT BY GAPS IN
CABINETS, IRS SPACE, SECOND FLOOR

PHOTO # 35



ROOM 1024, LARGE SAFE, INS SPACE ON FIRST FLOOR

PHOTO # 36



CRACK ON BOTTOM OF EIGHTH FLOOR SLAB.
PHOTO TAKEN WITHIN THE COE SPACE

PHOTO # 37




CRACK ON BOTTOM OF EIGHTH FLOOR SLAB.
PHOTO TAKEN WITHIN THE COE SPACE.

PHOTO # 38



CRACKS IN BOTTOM OF FIFTH FLOOR SLAB,
PHOTO TAKEN IN ROOM 4210

PHOTO # 39



CRACKS IN FOURTH FLOOR SLAB DIRECTLY UNDER ROOM 4408
PHOTO TAKEN WITHIN ROOM 3404

PHOTO # 40